

Sanitized Copy Approved for Release 2011/09/12: CIA-RDP85T00339R000100180002-4

CE	LDE.	r
-21	LINE	

NO FOREIGN DISSEM

25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

REFERENCE:

ATTACHMENT TO M-6062 20 MARCH 1969 PAGE 1

25X1

HOA LAC AIRFIELD NORTH VIETNAM 2101N 10530E

25X1

SIGNIFICANCE:

THIS BRIEFING BOARD DEPICTS THE RECENTLY COMPLETED RESURFACING OF THE MAIN RUNWAY, WITH PROBABLE RESURFACING OF THE PARALLEL TAXIWAY IN PROGRESS.

LOCATION:

1.4 NM WNW OF HOA LAC AND 6.3 NM SOUTH OF SON TAY.

BACKGROUND: 3.

PHOTOGRAPHY OBTAINED SUBSEQUENT TO THE LIMITED BOMBING HALT OF 1 APRIL 1968 HAS REVEALED A MAJOR EFFORT ON THE PART OF THE NORTH VIETNAMESE TO REPAIR AND IMPROVE THEIR AIRFIELDS. INTERMITTENT CONSTRUCTION AND REPAIR ACTIVITY HAS BEEN OBSERVED AT HOA LAC AIRFIELD SINCE THE LIMITED BOMBING HALT. THE PIERCED STEEL PLANKING (PSP) SURFACE MATERIAL ON THE RUNWAY AND TAXIWAY WAS REMOVED SUBSEQUENT TO THE AIRSTRIKES OF APRIL 1967. PHOTOGRAPHY OF JANUARY 1969 REVEALED A TRUCK-MOUNTED CRANE MOVING AND STACKING UNIDENTIFIED MATERIAL ALONG THE MAIN RUNWAY EDGE.

MISSION READOUT:

PHOTOGRAPHY

REVEALS THAT

THE MAIN (NW/SE) RUNWAY HAS BEEN RESURFACED WITH PROBABLE PSP. A CENTER SECTION OF THE PARALLEL TAXIWAY IS APPARENTLY BEING RESURFACED WITH PROBABLE PSP.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing boards (s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Imagery Exploitation Group NPIC.

GROUP IN EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION

SECRET

25X1

Sanitized Copy Approved for Release 2011/09/12: CIA-RDP85T00339R000100180002-4 **SECRET** NO FOREIGN DISSEM (c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER REFERENCE: ATTACHMENT TO M-6062 20 MARCH 1969 PAGE 2 POSSIBLE PSP SECTIONS ARE OBSERVED ALONG THE EDGE OF THE TAXIWAY. NEW RUNWAY MARKINGS ARE OBSERVED ON THE MAIN RUNWAY AND ON THE SECONDARY (EW) CONCRETE RUNWAY. THE NATURAL SURFACE (CONVERTED TAXIWAY) RUNWAY REMAINS UNCHANGED. AOB: 1 FISHBED 3 FRESCO 1 PROBABLE FAGOT 1 COLT REMARKS: HOA LAC IS NOW THE ONLY AIRFIELD IN NORTH VIETNAM WITH THREE SERVICEABLE RUNWAYS TWO OF WHICH ARE ALL WEATHER (ONE CONCRETE AND ONE PSP). HOA LAC IS THE

MAP REFERENCE: AMS SERIES L7014 SHEET 6051 II 1:50,000

SECOND AIRFIELD TO EMPLOY PSP AS A SURFACING MATERIAL SINCE

FIRST AIRFIELD TO USE PSP WAS BAI THUONG

AIRFIELDS

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing boards (s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Imagery Exploitation Group NPIC.

CONSISTENT WITH THE TREND OF THE NORTH VIETNAMESE TO REPAIR AND IMPROVE THEIR

SFCRFT

NO FOREIGN DISSEM

Sanitized Copy Approved for Release 2011/09/12 : CIA-RDP85T00339R000100180002-4

25X1

25X1

25X1

25X1

25X1

25X1

25X1

THE

THIS ACTIVITY IS

Sanitized Copy Approved for Release 2011/09/12 : CIA-RDP85T00339R000100180002-4

SECRET NO FOREIGN DISSEM




NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER



REPRODUCTION OF THIS DOC-UMENT IN WHOLE OR IN PART IS PROHIBITED EXCEPT WITH THE PERMISSION OF THE OFFICE OF ORIGIN.





25X1

25X1